



**Photo 1 – Overview of downstream face of dam from south end; note partially failed section circled in red**



**Photo 2 – Partially failed section of dam adjacent to spillway**



**Photo 3 – Overview of downstream face of spillway and north side of dam**



**Photo 4 – Overview of spillway weir; note sediment level is just below the weir**



**Photo 5 – Overview of dam crest from south end**



**Photo 6 – Overview of small impoundment area**